












ECX-TF













1a








		W mm	H mm	X mm
ECX C02		600	900	479
ECX C04		600	1000	543
ECX F06		700	1200	606
ECX M04		800	1000	543
ECX M06		800	1200	606
ECX M08		800	1400	676
ECX P04		1000	1000	543
ECX P10		1000	1500	740
ECX S06		1200	1200	606
ECX U04		1400	1000	543
ECX U08		1400	1400	676
ECX U10		1400	1500	740



1b





	 W mm	 H mm	X mm
ECX C02	600	940	479
ECX C04	600	1150	543
ECX F06	700	1360	606
ECX M04	800	1150	543
ECX M06	800	1360	606
ECX M08	800	1590	676
ECX P04	1000	1150	543
ECX P10	1000	1810	740
ECX S06	1200	1360	606
ECX U04	1400	1150	543
ECX U08	1400	1590	676
ECX U10	1400	1810	740

1c





			
	W mm	H mm	X mm
ECX C02	600	940	479
ECX C04	600	1150	543
ECX F06	700	1360	606
ECX M04	800	1150	543
ECX M06	800	1360	606
ECX M08	800	1590	676
ECX P04	1000	1150	543
ECX P10	1000	1810	740
ECX S06	1200	1360	606
ECX U04	1400	1150	543
ECX U08	1400	1590	676
ECX U10	1400	1810	740




2




3






4






5








6








7






8







9









10





11






12







13



14



15



AR: VELUX Argentina S.A. 3488 639944 / 45 / 46	EE: VELUX Eesti OÜ 621 7790	NZ: VELUX New Zealand Ltd. 0800 650 445
AT: VELUX Österreich GmbH 02245/32 3 50	ES: VELUX Spain, S.A. 91 509 71 00	PL: VELUX Polska Sp. z o.o. (022) 33 77 000 / 33 77 070
AU: VELUX Australia Pty. Ltd. 1300 859 856	FI: VELUX Suomi Oy 0207 290 800	PT: VELUX Portugal, Lda 21 880 00 60
BA: VELUX Bosna i Hercegovina d.o.o. 033/626 493, 626 494	FR: VELUX France 0821 02 15 15 0,119€ TTC/min	RO: VELUX România S.R.L. 0-8008-83589
BE: VELUX Belgium (010) 42.09.09	GB: VELUX Company Ltd. 01592 778 225	RS: VELUX Srbija d.o.o. 011 20 57 500
BG: VELUX Bulgaria EOOD 02/955 99 30	HR: VELUX Hrvatska d.o.o. 01/5555 444	RU: ЗАО VELUX (495) 737 75 20
BY: FE VELUX Roof Windows (017) 217 7385	HU: VELUX Magyarország Kft. (06/1) 436-0601	SE: VELUX Svenska AB 042/20 83 80
CA: VELUX Canada Inc. 1 800 88-VELUX (888-3589)	IE: VELUX Company Ltd. 01 848 8775	SI: VELUX Slovenija d.o.o. 01 724 68 68
CH: VELUX Schweiz AG 0848 945 549	IT: VELUX Italia s.p.a. 045/6173666	SK: VELUX Slovensko, s.r.o. (02) 33 000 555
CL: VELUX Chile Limitada 2 953 6789	JP: VELUX-Japan Ltd. 0570-00-8145	TR: VELUX Çatı Pencereleri Ticaret Limited Şirketi 0 216 302 54 10
CN: VELUX (CHINA) CO. LTD. 0316-607 27 27	LT: VELUX Lietuva, UAB (85) 270 91 01	UA: VELUX Ukraina TOV (044) 2916070
CZ: VELUX Česká republika, s.r.o. 531 015 511	LV: VELUX Latvia SIA 67 27 77 33	US: VELUX America Inc. 1-800-88-VELUX
DE: VELUX Deutschland GmbH 0180-333 33 99	NL: VELUX Nederland B.V. 030 - 6 629 629	
DK: VELUX Danmark A/S 45 16 45 16	NO: VELUX Norge AS 22 51 06 00	